KLUŚ **Inspiring Solutions**

Parts needed to mount the LOC-30 extrusion

Mounting strip (A)   Extrusion (B)   LED strip (C)   Cover (D)   Clip (E)   End cap (F)

Tools needed for mounting:

- drill
- screwdriver

WARNING! All LED strips should be connected to a 12 V or 24 V power supply.

IMPORTANT: The mounting instructions present the basic form of assembly.
More methods and related accessories can be found at www.KlusDesign.eu

KLUŚ Inspiring Solutions

1. Drill a hole in the mounting strip (A)

2. Attach the mounting strip to the mounting surface with suitable screws. Drill through the extrusion (B) to lead out the power cable.

3. Insert clips (E) into the extrusion (B), and then mount the LED strip (C) and lead out the power cable. The number of clips should be: 4 for 1-meter long profiles, 9 for 2-meters long profiles and 14 for 3-meters long profiles. First and last spring should be placed 5-7 cm from the end of the profile.

4. Insert the extrusion into the mounting strip, insert the cover (D) into the extrusion and insert the end cap (F)