

**Parts needed to mount the STEP extrusion**



Extrusion (A)



End cap (B)



LED strip (C)



Anti-slip  
rubber strip (D)



Cover (E)


**Tools needed for mounting:**

- drill
- screwdriver


**NOTE!** All LED strips must be connected to a 12 V or 24 V power supply.

**IMPORTANT:** The manual presents the simplest mounting procedure.  
More mounting procedures and related accessories can be found at [www.klusdesign.eu](http://www.klusdesign.eu)


**1.** Drill holes in the extrusion (A). At least two to mount the extrusion and at least one to run the power cable.




**2.** Attach the LED strips (C) and lead out the power cable. Next mount the extrusion (A) to the step with suitable screws.



**3.** Insert anti-slip rubber strips (D) into the extrusion. To do this, stretch the strip slightly or use a slippery substance. **NOTE:** After inserting the strip in the extrusion do not cut the excess length! It will slowly spring back to its former length.



**4.** Mount the cover (E) and connect the LED strips to the power supply.



**5.** Insert the end cap (B)

